2005 *JLC* Index

The 2005 *JLC* editorial index contains listings for feature articles, selected departments, product reviews, tool reviews, news stories, and letters. References are listed by topic rather than by article title. The following codes are used to help you find information:

* — In-depth coverage
L — Letter to the editor
Q — Question and answer
P — Product information

All of these articles are available on the *JLC* Archive CD/DVD, and most are available online at www.jlconline.com.

Accounting:
accrual vs. cash, and cost analysis, JAN:53
BuildWorks Basic and Quicken for accounting, FEB:37
profit and loss statements, JUN:43

Adhesives:
new glue replaces mortar (P), MAY:25
new plywood glue has no formaldehyde (P), SEP:29

Affordable housing, new rules in N.J. controversial, MAR:25

Air conditioning. *See* HVAC.

Air quality. *See* Indoor air quality.

Architecture: *See also* Design.
architects' responsibility for code, AUG:61; (L), NOV:21
Chinese post-and-beam house, JUN:160
draftsman uses deceased boss's license, AUG:29

Basements. *See* Foundations.

Bathrooms: *See also* Showers; Toilets.
annual innovative product picks*, JUL:91
faucet defect lawsuit, OCT:31
K/BIS show product highlights*, SEP:101

Bracing, brick wall support for wide-door installation*, JUN:55

Building standards. *See* Code, building.

Business: *See also* Accounting; Customers; Employees; Estimating; Legal; Marketing.
bidding system for large jobs*, JUN:93
builders help homeless, AUG:29
handyman business model choices, SEP:62
handyman service, operating, MAR:61; (L), JUL:19
impact fees rising, MAR:25
importance of operating legally, FEB:47
job journal for documentation, AUG:67
labor-hours, tracking with Excel pivot tables*, MAR:135
managing remodeling projects, APR:33
materials supply and prices, MAY:25
maturation via attitude shifts, OCT:63
newsletter for client contact, NOV:65
preconstruction checklist to avoid problems*, SEP:93
remodeling cost grid and customer expectations, JUL:61
retirement issues, MAY:63
tax break for construction, DEC:29
tracking income with spreadsheet, MAR:66
unlicensed contractors in Ariz., FEB:21; (L), APR:13

Carbon monoxide. *See* Heating, gas; HVAC.

Carpet, over radiant slab (Q), APR:29

Ceramic tile:
backsplash design guidelines, SEP:117
for breezeway floor (Q), MAY:33
setting toilet over (Q), APR:29
shower bench, installing, NOV:123

Charitable practice, developer helps homeless, AUG:29

Chimneys, concrete cap for*, MAY:89

Code, building:
and N.J. investigative report, MAY:25; (L), AUG:21; (L), NOV:21
architects' responsibility for code, AUG:61; (L), NOV:21
energy code criticized by DOE, APR:21; (L): JUL:19; (L), OCT:21
IBC in Calif., JUN:25
SIPs prescriptive method in development, MAR:25
supporting (L), JAN:19
unvented attics and code, MAY:25

Compressors, tandem (L), FEB:17

Computers. *See* Computer software; Internet.

Computer software:
BuildWorks Basic and Quicken for accounting, FEB:37
Excel pivot tables for tracking labor-hours*, MAR:135

Concrete:
adapted for toboggans, APR:160
bowed basement wall problem (Q), AUG:45
curing in hot weather (Q), JAN:37
exposed aggregrate*, JAN:77
glue as mortar replacement (P), MAY:25
ICF swimming pool, OCT:176
piers, smooth finish for, AUG:53
pool survives landslide, MAY:25

Conservation. *See* Environment; Green building.

Contracts. *See* Legal.

Crawlspaces:
flooring choices in humid climates and (Q), JUL:35
free design guide for unvented, DEC:29
in attic, FEB:128
LVL rot in crawlspaces (Q), SEP:43

Customers, expectations and remodeling cost grid, JUL:61

Decks: *See also* Framing, decks; Porches.
prefab galvanized hardware for rail-post connections*, FEB:65; (L), APR:13; (L), MAY:19; (L), JUN:15
protecting during construction, DEC:47
resisting rot, details for*, APR:77
wood-plastic composite decking and rot and decay (L), DEC:19

Design: *See also* Architects.
bay window guidelines, JUL:49
eaves and rake details, MAR:49
enclosing a porch, NOV:53
interior trim, MAY:53

Developers:
homeowners associations lawsuits and, FEB:21
impact fees rising, MAR:25

Doors:
pocket-door installation trick, AUG:53
protecting in wet climates*, SEP:83
wide-door installation and brick-wall support*, JUN:55

2005 *JLC* Index

Drainage. *See* Foundations; Exteriors; Moisture.

Drywall:
installing on knee walls (Q), SEP:43
layering for decorative effect*, SEP:111
vertical installation of (Q), JAN:37

Electrical:
adjustable electrical box, NOV:45
number of receptacles per circuit (Q), SEP:43
sprinklers mandated, MAY:25; (L), OCT:21; (L), NOV:21
stray voltage in swimming pool (L), JAN:19
structured wiring for home automation*, MAY:97; (L), SEP:19
surge arrestor and good customer service (L), AUG:21
two-wire circuits, bringing to code (Q), NOV:39

Employees:
firing legally, JUN:49
hiring with group interviews, APR:33
Hispanic, in trades (L), FEB:17
interviewing by crew members, DEC:51
labor shortage and minorities (L), APR:13; (L), JUN:15; (L), JUL:19
learning Spanish for the job site*, AUG:113; (L), OCT:21; (L), DEC:19
military service and, JAN:61
need for trade schools (L), FEB:17; (L), APR:13
overtime pay laws, APR:45
Spanish-speaking, and handbooks for (Q), NOV:39
theft problems, preventing, OCT:63

Energy: *See also* Solar power.
code amendments criticized by DOE, APR:21; (L), JUL:19; (L), OCT:21
conference, MAR:25
Energy Policy Act of 2005 incentives, OCT:31

Engineered lumber: *See also* Lumber.
cupped LVL (L), JAN:19
I-joists with plywood webs (Q), OCT:45
LVL rot in crawlspaces (Q), SEP:43

Environment: *See also* Green building; Solar power.
biodiesel truck fuel, AUG:152
Calif. energy-efficient lighting law and builders' costs, JAN:25
developer/environmentalist lawsuit, APR:21
waterfront project and lawsuit, JAN:25

Estimating:
job-costing for accurate, MAY:41
unit-cost assemblies for, FEB:30

Exteriors: *See also* Gutters.
annual innovative product picks*, JUL:91
curved trim, installing*, MAY:81
flashing details for flanged windows*, JUN:65; (L), SEP:19; (L), OCT:21
glazed cupola, shop-built, installation*, NOV:97
manufactured stone over ICFs*, JUL:109
manufactured-stone veneer and moisture problems (L), MAR:19
permanent coatings, JAN:25
stairs, building with housed-stringer method*, NOV:115
vapor barrier behind brick veneer (L), MAR:19

Fasteners: *See also* Anchors.
connectors, free training kit, NOV:27
for MDF products (Q), AUG:45

Finish carpentry:
closet assembly and installation with melamine*, JUN:75
dado blades for drawer boxes, SEP:51
manufactured bullnose corners, JUL:41

Fireplaces:
masonry heaters (L), MAR:19
surround design for, JAN:43

Fire restoration. *See* Insurance restoration.

Flashing:
details for flanged window installation*, JUN:65; (L), SEP:19; (L), OCT:21
pan flashing for stone sill, NOV:45

Floor finishes, peeling from hardwood (Q), DEC:39

Flooring: *See also* Floor finishes.
hardwood, refinishing (Q), MAY:33
laminate choices and tips*, FEB:81
over crawlspace in humid climate (Q), JUL:35

Foundations: *See also* Crawlspaces; Slabs.
adding window in block foundation (Q), APR:29
annual innovative product picks*, JUL:91
bowed basement wall problem (Q), AUG:45
cement shortage, OCT:31
lally columns replace masonry piers in basement, OCT:51
mat foundation for beach house*, OCT:93; (L), DEC:19
plastic footing form and perimeter drain*, MAR:113
walk-out basement addition, supporting brick veneer for*, MAR:81
wet basements and interior perimeter drainage*, DEC:77

Framing: *See also* Framing, deck; Framing, roof.
annual innovative product picks*, JUL:91
curved portico with full-scale layout and synthetic millwork*, DEC:57
header detail, DEC:47
SIP floors, installing*, APR:67
SIPs prescriptive method in development, MAR:25

Framing, deck:
accounting for snow loads (L), NOV:21
prefab galvanized hardware for rail-post connections*, FEB:65; (L), APR:13; (L), MAY:19; (L), JUN:15; (L) AUG:21

Framing, roof:
barrel-vault ceilings*, AUG:75
cathedral hip roof (L), FEB:17
stick-framed with timber rafter tails*, SEP:73; (L), NOV:21; (L), DEC:19
truss-rolling trick, JUL:41

Glue. *See* Adhesives.

Green building: *See also* Environment.
grass-topped roofing, MAY:160
programs with residential factors (L), MAR:19

Gutters, integral, in rafter tail add-on, SEP:73; (L), NOV:21

Handyman business:
operating, MAR:61; (L), JUL:19
to specialize or not, SEP:62

Heating and cooling, ground-source heat pumps and direct-exchange technology*, FEB:73; (L), JUN:15

Heating, gas:
CO death and defective plastic vent pipe, APR:21; (L), JUN:15
CO death findings and new legislation, JUL:27
CO scare with snow-covered vent pipes (L), AUG:21
gas fireplace recall, SEP:29
unvented heaters and asthma study, MAR:25

Heating, hydronic, and radiant tubing leak (Q), JUN:37

Home inspection, privatization in Houston, FEB:21

Housing market:
boom and affordability, AUG: 29
insights on real estate boom, JUL:27
second home sales on rise, JUN:25

Hurricanes: *See also* Wind.
Fla. roof woes from '04, JUN:25
Fla. wall moisture problems from '04, JAN:25

2005 *JLC* Index

Katrina: one carpenter's story, NOV:27
Katrina's damage estimates, OCT:31
new products and, FEB:21
strength of framing lumber after flooding (Q), NOV:39
stucco homes and water intrusion from '04*, JUL:79; (L), SEP:19
tarp costs, DEC:29

HVAC: *See also* Heating; Ventilation.
air conditioner noise and soundproofing (Q), JUN:37
air conditioning for humid climates (L), JAN:19, MAR:19
annual innovative product picks*, JUL:91
CO death and defective plastic vent pipe, APR:21; (L), JUN:15
CO death findings and new legislation, JUL:27
CO scare with snow-covered vent pipes (L), AUG:21
energy performance conference, MAR:25
ground-source heat pumps, direct-exchange technology and*, FEB:73; (L), JUN:15

Ice buildup, roof repair and prevention of, APR:21; (L), JUL:19

Indoor air quality:
fumes in living space from attached garage (Q), OCT:45
removing cigarette-smoke odor (Q), JUL:35
unvented heaters and asthma study, MAR:25

Insulation, best method for kneewalls (Q), SEP:43

Insurance: *See also* Business.
health savings accounts for cost savings, SEP:57
homeowners' and remodeling coverage, NOV:65
roofers not providing workers' comp in Fla., NOV:27
title-company settlement refunds to homeowners, JUL:27
workers' comp reform in Texas, SEP:29

Insurance restoration:
advice on getting into*, FEB:91; (L), APR:13
assessing and repairing fire-damaged homes*, MAR:123; (L), JUN:15

Interiors:
annual innovative product picks*, JUL:91
finishing closets with melamine*, JUN:75
pocket-door installation trick, AUG:53
wallpaper prep (Q), AUG:45; (L), OCT:21; (L), DEC:19

Internet, via WiFi network, OCT:51

Jigs, cabinet pull layout, APR:13

Job sites, sandy, wooden walkway for working on, DEC:47

Kitchens:
annual innovative product picks*, JUL:91
K/BIS show product highlights*, SEP:101
tile backsplashes, SEP:117

Laser levels. *See* Tools & Equipment.

Lawsuits:
Chicago porch collapse countersuit, MAR:25
environmental suit in Texas, APR:21
faucet defect suit, OCT:31
homeowners associations sue developers, FEB:21
lead paint suit and pamphlet rule enforced by penalty, NOV:27
safety inspection dispute in Wash., FEB:21
title insurer settlement refunds to homeowners, JUL:27
water damage suit and torn-down house, NOV:27
waterfront project and arcane law, JAN:25

Lead paint:
hazard is real (L), JAN:19
lawsuit; pamphlet rule enforced by penalty, NOV:27

Legal: *See also* Business; Insurance; Lawsuits.
architects' responsibility for code, AUG:61; (L), NOV:21
builder arrested for violating housing codes, APR:21
buy-sell agreements, SEP:67
Calif. energy-efficient lighting law and builders' costs, JAN:25
CO death findings and new legislation, JUL:27
contracts, breach of, MAR:71
dispute over retaining wall, MAR:25
eminent domain ruling by Supreme Court, AUG:29
firing employees legally, JUN:49
HBA and zoning dispute in Ore., APR:21
job journal for documentation, AUG:67
mold issues, NOV:73
overtime pay laws, APR:45
retirement and closing a business, MAY:63
Spanish-speaking, and employee handbooks for (Q), NOV:39

Liability. *See* Legal.

Lighting, law in Calif., JAN:25

Lumber: *See also* Engineered lumber.
framing, strength after flood waters (Q), NOV:39
strength and age (Q), JAN:37
trading Web site, OCT:31

Marketing: *See also* Business.
marketing plan for stronger business*, NOV:105
VW bugs as advertising vehicle, DEC:29

Masonry, cleaning brick, SEP:51

Materials:
lumber supplier with builder focus, SEP:29
supply and prices, MAY:25

Moisture: *See also* Mold.
door and window protection in wet climates*, SEP:83
LVL rot in crawlspaces (Q), SEP:43
vapor barrier behind brick veneer (L), MAR:19

Mold, and legal issues, NOV:73

Nailers:
coil framing, test and comparison*, DEC:67
cordless finish, comparison*, APR:87
high-pressure, review, JAN:119
paper-collated clipped-head, review*, MAR:91
pneumatic, tuning up*, JUN:85
round-head framing, review, OCT:157

Paints and finishes:
oil-based, present status and future of*, JAN:97
prep and technique for cedar shingles (Q), MAY:33
recycling latex, AUG:29
waterborne lacquer, spraying with pressure pot*, OCT:127

Photovoltaics. *See* Solar power.

Plumbing:
air-admittance vents, installing, JUN:103
problem-solving devices*, NOV:89

Porches, design for enclosing, NOV:53

Radon, informational resource (L), JAN:19

Recycled materials. *See* Salvage.

Remodeling:
assessing and repairing fire-damaged homes*, MAR:123; (L), JUN:15
cost grid and customer expectations, JUL:61
dust-control system, NOV:45

garage with sculptural steel columns

2005 *JLC* Index

and beams for wide-span floor*, OCT:107
insurance coverage from clients' policy, NOV:65
insurance restoration, advice on getting into*, FEB:91; (L), APR:13
lifting house and raising ceilings*, MAY:71
project management for, APR:33
roof demo with crane, OCT:51
understair pantry, DEC:47

Roofing:
annual innovative product picks*, JUL:91
asphalt, and nail pops (Q), OCT:45
BUR hot-mop, materials and installation*, FEB:55; (L), MAY:19
grass-topped, MAY:160
post-hurricane roof woes in Fla., JUN:25
slate, new batten and clip system for*, JUL:68
solar, JUN:37

Roofs. *See* Framing, roofs.

Safety, job-site:
cautionary first-hand stories*, AUG:95; (L), OCT:21
circ saw blade-guard recall, JUL:27
gas fireplace recall, SEP:29
inspection dispute in Wash., FEB:21
magazine covers criticized (L), DEC:19
table saw recall, MAR:25

Salvage, latex paint recycling, AUG:29

Saws:
circular saw blade-guard recall, JUL:27
circular saw review, SEP:129
cordless jigsaw review, APR:131
dado blades for drawer boxes, SEP:51
miter, with laser, DEC:105
reciprocating saw review, AUG:137
table saw recall, MAR:25
wormdrive, review, JUL:131

Scaffolding, frame, or "pipe," erecting correctly*, JAN:85

Septic, problems with new systems, NOV:27

Shelter, job-site, geodesic dome for, JAN:144

Showers:
tiled bench, installing, NOV:123
waterproofing system for, APR:105

Siding:
annual innovative product picks*, JUL:91
manufactured stone over ICFs*, JUL:109
manufactured-stone veneer and moisture problems (L), MAR:19
underlayment beneath cedar shakes (Q), NOV:39
vinyl installer's certification program (L), OCT:21

SIPs. *See* Framing.

Sitework:
compact excavator, purchasing pros and cons*, AUG:87
plastic footing form and perimeter drain*, MAR:113

Slabs:
exposed aggregrate*, JAN:77
post-tensioned design explained (Q), JUL:35
post-tensioned, precautions for tearing out (Q), MAR:43; (L), JUN:15
radiant, carpet over (Q), APR:29

Smart house, prefabricated utility wall, FEB:21

Software. *See* Computer software.

Solar power:
college design and build competition, DEC:29
photovoltaic system, sizing and installing*, MAR:103
PV modules in place of roof shingles (Q), JUN:37
water heating systems*, OCT:79

Soundproofing:
air conditioner noise and (Q), JUN:37
condo common walls and (Q), DEC:39

Spanish-speaking employees. *See* Employees.

Sprinklers. *See* Electrical.

Staging. *See* Scaffolding.

Stairs:
box newel design, construction, and installation*, AUG:105
exterior, with housed-stringer method*, NOV:115
full-scale layout for winders*, APR:55
three-story continuous handrail, DEC:120

Steel, braces for wide door installation*, JUN:55

Storage, understair pantry, DEC:47

Structural:
brick wall support for wide-door installation*, JUN:55
Chicago porch collapse countersuit, MAR:25
concrete piers, smooth finish for, AUG:53
lifting house and raising ceilings*, MAY:71
prefab galvanized hardware for deck connections*, FEB:65; (L), APR:13; (L), MAY:19; (L), JUN:15; (L) AUG:21
sculptural steel columns and beams for wide-span floor*, OCT:107
soffit vents and load transfer (Q), MAR:43
walk-out basement addition, supporting brick veneer for*, MAR:81

Stucco:
trim, rehabbing with rainproofing details*, OCT:119
walls and water intrusion from hurricanes*, JUL:79; (L), SEP:19

Theft, problems with employees, preventing, OCT:63

Tile. *See* Ceramic tile.

Toilets: *See also* Plumbing.
low-flow flush tests and soy test media, SEP:152
setting over tile (Q), APR:29

Tools & Equipment: *See also* Compressors; Jigs; Nailers; Saws.
annual innovative product picks*, JUL:91
biodiesel truck fuel, AUG:152
chalk lines and ink lines review (P), APR:131
clamps for column install, JUL:41
compact excavator, purchasing pros and cons*, AUG:87
demolition hammer review, FEB:115
door planer overview and comparison*, JUL:101
drywall screw-gun review, MAR:173
laser level, self-leveling, review (P), APR:131
laser plumb-bob review, JUN:130
layup table, expandable, and saw guide, review, NOV:135
mini skid-steer loaders, MAY:107
rotary hammers, combination, test and comparison*, NOV:79
rotary hammers, compact, test and comparison*, MAY:107
satellite radio truck setup, JUL:144
table saw recall, MAR:25
truck tailgate-related deaths, JUN:15

Trim, exterior:
cellular PVC, compressive strength of (Q), DEC:39
installation of curved*, MAY:81

Trim, interior: *See also* Finish carpentry; Interiors.
designing with, MAY:53
traditional for windows*, DEC:85

Ventilation. *See* HVAC; Indoor air quality.

Ventilation, roof:
attic mold and (L), FEB:17
ridge vents and wind (Q), JUN:37
soffit vents and load transfer (Q), MAR:43; (L), JUL:19
unvented attics and code, MAY:25

Vinyl. *See* Siding.

Water heaters:
efficiency of (L), FEB:17
hot-water recirculation loop, AUG:121
solar systems*, OCT:79

Waterproofing:
guidelines from Fla. builders' group, MAR:25; (L), JUN:15
pan flashing for stone sill, NOV:45

Wildfires, risks and Calif. response, JAN:25

Wind: *See also* Hurricanes.
tornadoes, resisting with structural connections (L), JAN:19

Windows:
adding in block foundation (Q), APR:29
bay, design guidelines for, JUL:49
flanged, flashing installation details*, JUN:65; (L), SEP:19; (L), OCT:21
impact-resistant, energy ratings for (L), JAN:19
protecting from moisture*, SEP:83
traditional trim for*, DEC:85
traditional wood, installing to prevent failure*, APR:93

Workers' compensation. *See* Insurance.