

2011 JLC Index

The 2011 JLC editorial index contains listings for feature articles, selected departments, product reviews, tool reviews, news stories, and letters. References are listed by topic rather than by article title. The following codes are used to help you find information:

- * — In-depth coverage
- L — Letter to the editor
- Q — Question and answer
- P — Product information

All of these articles are available on the JLC Archive DVD, and most are available online at jlonline.com.

Accessibility:

apartment remodel to meet HUD requirements*, SEP:67

closet carousel, accessible (P), NOV:65

Accounting: See Bookkeeping; Business.

Additions: See Remodeling.

Air conditioning: See Hvac.

Air-sealing: See also Energy efficiency.

caulk, colored (P), SEP:81

ice dam repair, creating profitable sideline with*, JAN:29; (L) MAR:15; (L) APR:17; (L) MAY:15; (L) JUL:13

Appliances:

dishwasher, deep drawer-style (P), JAN:63

double oven, efficient (P), NOV:65

dryer duct booster (P), OCT:75

gas cooktop, compact (P), NOV:65

range hood, retractable (P), NOV:65

refrigerator, drawer-style (P), JAN:63

washing machine hoses, leakproof (P), FEB:69

Architecture: See Design.

Asphalt shingles: See Roofing.

Attics, stacking joists for living space expansion (Q), OCT:25

Barn, reassembling on new site, SEP:96

Basements: See Foundations.

Bathrooms: See also Showers and tubs; Toilets;

Ventilation, mechanical.

adding bath, expanding bedrooms in small house, APR:31

custom decorative tiles from artist-renovator, JUN:96

glass tile, recycled (P), OCT:75

reproduction dresser/vanities (P), FEB:69

sink-drain kit, easy (P), JUN:75

Bookkeeping, time-clock system for easier payroll, job-costing, and estimating*, FEB:61

Brick veneer: See Siding.

Building standards: See Code, building.

Business: See also Economy; Employees; Legal; Marketing.

1099 tax provision to be repealed, MAR:17

alternatives to the bidding process, APR:35; (L) JUN:17

annual strategic planning, steps for, DEC:23

budget calculator, using to ID right number of sales leads, JAN:23

controlling growth with value and selling price, JUN:37

gross profit and lowering direct costs, MAR:25

Harvard reports remodeling comeback, APR:19

"lean" principles and practices for less waste, more profit, FEB:37

OSHA regs and fines unmanageable (L), MAY:15

PEOs, outsourcing employee administration to, MAY:19

purchasing system, basics for reaching target profit, JUL:33

purchasing system, details for implementing, SEP:35

purchasing system, job-cost variances, change orders, and allowances, NOV:29

RRP organizer and forms (P), MAR:73

smartphone saves money for geezer (L), SEP:13

time-clock system for easier payroll, job-costing, and estimating*, FEB:61

Cabinets:

base cabinet, waterproof polymer (P), JUL:81

pulls, decorative (P), SEP:81

Ceramic tile:

custom decorative tiles from artist-renovator, JUN:96

double-plywood substrate and load-bearing membrane, details for*, MAR:45

double-sided tape for setting tile (P), APR:73

grout, GreenGuard-certified (P), AUG:65

made from recycled bath fixtures (P), APR:73

self-leveling cement underlayment, overview and installation details*, APR:57

tile mats, adhesive (P), NOV:65

Chimneys:

chase, rotten, and details for proper drainage plane, NOV:23

finishing top of framed chase (Q), APR:27; (L) OCT:13

vent pipe boot (P), MAR:73

Code, building:

builder fined for fall-protection violations, NOV:19

deck requirements per 2009 IRC, overview and details*, JUN:69

energy code challenge rejected in Wash., APR:19

Fla. code to regulate advertising language, SEP:17

ICC 500 storm shelter code coming into use with demand, AUG:17

International Energy Efficiency Code approved by ICC, JAN:15

IRC sprinkler regs rejected in Mich., FEB:19

IRC sprinkler regs repealed in Pa., JUN:25

Maine code intact, JUN:25

Nev. to ramp up OSHA citations, SEP:17

OSHA fall-protection regs, delay in reinstating, AUG:17

OSHA fall-protection regs, legal challenge rejected, JUN:25

OSHA fall-protection regs reinstated, FEB:19;

MAR:17; (L) MAY:15

proposal for relaxed fire regs in N.C., FEB:19

PT lumber in dry connections to concrete and masonry (Q), DEC:15

regulation costs claimed in NAHB paper, SEP:17

Wichita to beef up foundation code, SEP:17

winder stair layout and code compliance (L), MAR:15

Computers, microdata centers in basements could heat houses, SEP:17

Computer software:

SketchUp, builder reviews and experiences*, DEC:35

template language left in Intuit-based websites, JUL:21 15

Concrete:

garage slabs, details for strong, crack-free jobs*, MAY:53; (L) AUG:13

vibrator, small (P), SEP:91

Conservation: See Energy efficiency; Environment; Solar power; Wind power.

Countertops:

lava-slab (P), SEP:81

stone-look laminate (P), SEP:81

Covered bridge, lattice truss, built for wedding, JAN:80

Crawlspaces: See Foundations.

Decks: See also Porches; Structural.

deck collapses, OCT:15

deck requirements per 2009 IRC, overview and details*, JUN:69

freestanding deck, methods for stabilizing*, DEC:27

girders, connecting to deck ledgers (Q), SEP:25

polymer resurfacer (P), JAN:63

post wrap, prefab (P), DEC:65

PVC, affordable (P), DEC:65

redwood (P), SEP:81

Sonotube installation under decks and porches, FEB:31

Trex, coated (P), DEC:65

Defects:

Chinese drywall, NAHB advice questioned, MAY:19

Chinese drywall repair guidelines, updated, NOV:19

Chinese drywall settlement expected, AUG:17

deck collapses, OCT:15

Design:

adding bath, expanding bedrooms in small house, APR:31

narrow third-floor apartment, redesign for openness and storage*, MAY:61

Passive House concept, overview of, FEB:19

Passivhaus Institute severs ties with U.S. institute, OCT:15

SketchUp, builder reviews and experiences*, DEC:35

Disputes:

See Legal.

Doors:

fiberboard from wheat straw (P), NOV:65

frame, rot- and insect-resistant (P), NOV:65

heavy, steps for solo installation of*, OCT:47

mahogany, custom (P), JUN:75

patio, fold-away (P), JAN:63

porch enclosure with aluminum storm door panels, FEB:31

stop, hinge-pin (P), JUN:75

Drainage: See Exteriors; Foundations; Siding.

Drywall:

air-cleaning (P), MAR:73

Chinese drywall, NAHB advice questioned, MAY:19

Chinese drywall repair guidelines, updated, NOV:19

Chinese drywall settlement expected, AUG:17

corner tape, flexible (P), MAR:73

hanging, tips and tools for working solo*, NOV:44

moisture-resistant (P), MAR:73

repair adhesive (P), MAR:73

rough, showing through paint (Q), FEB:29

textured, patch template (P), MAY:85

Economy:

copper thefts rampant, SEP:17

Harvard reports remodeling comeback, APR:19

high-performance homes, affordable, installation details for*, JAN:39

home built with U.S. products only, OCT:15

homeowners still value ownership, JUN:25

multigenerational households, remodeling for, NOV:19

SAVE Act to value energy upgrades in mortgage underwriting, APR:19

timber-frame barn, built with tech ed students in slow economy, DEC:80

Electrical:

boxes, in stucco, flashing technique, AUG:29

charging system, residential (P), JUL:81

outlet strip, pop-up (P), SEP:81

receptacles, unobtrusive (P), OCT:75

wiring, flat (P), NOV:65

Employees:

PEOs, outsourcing employee administration to, MAY:19

time-clock system for easier payroll, job-costing, and estimating*, FEB:61

Energy efficiency: See also Solar power; Wind power.

attic insulation for hot climates (Q), SEP:25; (L) NOV:15

Calif. and others haven't spent fed. funds, SEP:17

crews, skills competition in W.Va., JUL:96

energy code challenge rejected in Wash., APR:19

energy conservation ordinance considered by cities, APR:19

2011 JLC Index

energy retrofit of small house in three phases*, JUL:43
Energy Star 2011 standards misleading (L), JAN:13
exterior spray foam and airtight shell for almost net-zero home*, MAY:35; (L) JUL:13; (L) SEP:13
fiber-cement siding replacement and energy upgrade*, SEP:57; (L) DEC:13
high-performance homes, affordable, installation details for*, JAN:39
infrared imaging, overview, interpreting, and inspections with*, NOV:33
insulation retrofit from outside with rigid foam*, JUN:43; (L) JUL:13
International Energy Efficiency Code approved by ICC, JAN:15
LEED false advertising suit dismissed, OCT:15
N.M. governor and code upgrades, JUL:21
Passive House, case study and installation details*, AUG:35; (L) DEC:13
Passive House concept, overview of, FEB:19
Passivhaus Institute severs ties with U.S. institute, OCT:15
SAVE Act to value energy upgrades in mortgage underwriting, APR:19
weather seals (P), SEP:81
window glazing area recommendations (Q), APR:27
window replacement, installation profile, SEP:29
windows, replacement, guide to understanding and choosing*, OCT:65
zero-carbon house with wind and geothermal (L), JAN:13

Environment: *See also* Energy efficiency; Solar power; Wind power.
ceramic tile from recycled fixtures (P), APR:73
EPA RRP, getting on board with, JAN:15; (L) MAR:15; (L) APR:17
garage doors, recycled Douglas fir (P), APR:73
glass tile, recycled (P), OCT:75
smog-eating tile roofs in Calif., MAR:17
standing-seam roof, restoring with elastomeric membrane*, FEB:55

Exteriors: *See also* Gutters; Porches; Siding; Stucco.
bulkhead doors, replacing, with PT wood and cellular PVC*, NOV:51
cedar shingle siding, installation details for*, MAR:33
chimney chase, rotten, and details for proper drainage plane, NOV:23
column, split, steel-post, installing for porch roof support, DEC:19
EIFS sidewall detail (L), FEB:15
floating patio deck tile (P), DEC:65
hillside elevator, AUG:80
housewrap, liquid (P), FEB:69
insulation retrofit from outside with rigid foam*, JUN:43; (L) JUL:13
paver patio, installing, OCT:29
pavers, recycled-material (P), AUG:65
porch enclosure with aluminum storm door panels, FEB:31
porch rehab, from concrete piers to roof*, MAR:65
sheathing, weather-barrier (P), DEC:65
shutters, quick stile production with homemade jig, MAY:25
shutters, transparent (P), JUN:75
trim, reversible (P), JUL:81
Zip System sheathing panels, overview and installation details*, FEB:47; (L) JUN:17; (L) JUL:13

Fiber cement: *See* Siding.

Finish carpentry: *See also* Stairs.
crown molding jig (P), JUN:89
crown, premitered (P), NOV:65
curved handrail, forming, and finessing the transitions*, JUL:55
drop ceiling, wood-look (P), AUG:65
radius trim for arched pediment, OCT:53
wood glue, driplless (P), NOV:65

Fire resistance, tape, self-adhesive (P), OCT:75

Fire safety:
fire doors, auto-release, in condo expansion*, AUG:61; (L) OCT:13
fire escape, flexible, in wall cabinet, JAN:63
IRC sprinkler regs rejected in Mich., FEB:19
IRC sprinkler regs repealed in Pa., JUN:25
natural gas odor fade and explosions, APR:19
proposal for relaxed regs in N.C., FEB:19
spray foam and risk of fire, OCT:15; (L) DEC:13

Flooring: *See* Wood flooring.

Floors:
double-plywood substrate and load-bearing membrane under ceramic tile*, MAR:45
floor adhesive, removable (P), OCT:75
self-leveling cement under tile, installation details for*, APR:57
squeaky, fix for (Q), JUN:31
subfloor, floodproof (P), AUG:65
subfloor, snap-together (P), JUN:75

Foundations:
bulkhead doors, replacing, with PT wood and cellular PVC*, NOV:51
crawlspaces, sealing with polyethylene and duct mastic (L), JUN:17
footer forms, polyethylene (P), JUL:81
garage slabs, details for strong, crack-free jobs*, MAY:53; (L) AUG:13
hillside, failed, correcting with helical piers, beam, and steel cap plates*, DEC:49
masonry bit, tough (P), JUL:91
perimeter drain, low-profile (P), MAR:73
permanent wood foundations, installation details*, JUN:59; (L) AUG:13
porch rehab, from concrete piers to roof*, MAR:65
PT lumber in dry connections to concrete and masonry (Q), DEC:15
rammed-earth walls in upscale homes, OCT:96
Sonotube installation under decks and porches, FEB:31

Framing: *See also* Framing, roof; Framing, wall.
curved arches, prefab (P), APR:73
insulated materials (P), APR:73
nail gun comparison and review*, APR:66
stairs, elliptical, using a trammel to scribe*, APR:49
stair winders, wedge-shaped boxes for, OCT:29
straps, compression and tension (P), JUL:81
studs, plastic (P), MAY:69

Framing, roof:
dormer, prefab, details for building on ground and lifting*, DEC:59
H-clips, pliable nylon (P), MAY:69
SIPs, how far to cantilever (Q), APR:27
spreading roof fix, with horizontal beam and steel tie rod retrofit*, FEB:39
valley truss clip, (P), JAN:63

Framing, wall, OSB, gluing studs and buckle (L), JUN:17; (L) SEP:13

Garages:
concrete slabs, details for strong, crack-free jobs*, MAY:53; (L) AUG:13
doors, faux finishes on, APR:88
doors, recycled Douglas fir (P), APR:73
doors, wood-look (P), APR:73

Geothermal:
with hot groundwater, MAY:88
zero-carbon house with wind and geothermal (L), JAN:13

Glass tile, recycled (P), OCT:75

Gutters:
for new construction (P), JUN:75
with oversized water outlets (P), MAR:73

Hardware:
for movable bookcase (P), JUN:75
overhead cabinet, easy-open (P), SEP:81
sliding door hardware, wall-mounted (P), JAN:63

Housing market:
banks demolish foreclosed houses, SEP:17
energy conservation ordinance considered by cities, APR:19
homes with solar sell for more, JUL:21
incentives backfired on homeowners, JUL:21
SAVE Act to value energy upgrades in mortgage underwriting, APR:19

Hurricanes: *See* Storms and storm damage.

Hvac:
condensing boiler, efficient (P), OCT:75
floor heat cable, moisture-resistant (P), OCT:75
geothermal with hot groundwater, MAY:88
hydronic, integrated (P), MAY:69
hydronic system design, multi-source*, AUG:53
natural gas odor fade and explosions, APR:19
pressure balancer, door-grille (P), DEC:65

Ice dams, profitable sideline from repair of*, JAN:29; (L) MAR:15; (L) APR:17; (L) MAY:15; (L) JUL:13

Insulation:
attic, for hot climates (Q), SEP:25; (L) NOV:15
dried eelgrass insulation, NOV:80
energy retrofit, small house, in three phases*, JUL:43
exterior spray foam and airtight shell for almost net-zero home*, MAY:35; (L) JUL:13; (L) SEP:13
fiber-cement siding replacement and energy upgrade*, SEP:57; (L) DEC:13
infrared imaging, overview, interpreting, and inspections*, NOV:33
polyester, no-VOC (P), MAY:69
retrofit, from outside with rigid foam*, JUN:43; (L) JUL:13
spray foam, and risk of fire, OCT:15; (L) DEC:13
spray foam, gentle (P), JUN:75

Interiors:
barnboards, old, prepping to re-use (Q), JUN:31
clay earth plasters, job profile, JUL:27
heavy doors, steps for solo installation of*, OCT:47
high-quality finish for mixed substrates, details for*, OCT:53
recycled trim (P), JUN:75
stone-look panels (P), DEC:65

Jigs:
crown molding (P), JUN:89
jigs and tools for building stairs*, JAN:48

Kitchens: *See also* Cabinets.
custom decorative tiles from artist-renovator, JUN:96
expansion project, removing bearing wall for*, AUG:45; (L) NOV:15
glass tile, recycled (P), OCT:75

Lawsuits: *See* Legal.

Lead paint:
contractor pays huge fine, MAY:19
DVD, compliance and methods, AUG:65
EPA drops clearance requirement, SEP:17
power scrapers, comparison and review*, MAR:57
RRP, getting on board with, JAN:15; (L) MAR:15; (L) APR:17
RRP organizer and forms (P), MAR:73
RRP violator caught on YouTube and cited, JUL:21
soil levels and vegetable gardening (Q), AUG:27
test kit (P), MAY:69

Legal: *See also* Business.
Chinese drywall settlement expected, AUG:17
Colo. mandates new home options, APR:19
energy code challenge rejected in Wash., APR:19
LEED false advertising suit dismissed, OCT:15
N.J. builders charged for no state registrations, JUN:25
N.M. governor and energy code upgrades, JUL:21
OSHA fall-protection regs, delay in reinstating, AUG:17
OSHA fall-protection regs, legal challenge rejected, JUN:25
RRP violator caught on YouTube and cited, JUL:21
S.C. holds builders liable for defects, MAR:17

Lighting:

can light hole saw (P), MAY:85
 can lights, efficient (P), FEB:69
 fan lights, efficient (P), AUG:65
 LED replacement bulb (P), AUG:65
 LEDs, affordable (P), OCT:75
 LEDs, cheaper (P), JUN:75
 outdoor, kit (P), MAY:69
 recessed light covers (P), MAY:69

Lumber, PT, in dry connections to concrete and masonry (Q), DEC:15

Marketing:

alternatives to the bidding process, APR:35
 budget calculator, using to ID right number of sales leads, JAN:23

Materials:

copper thefts rampant, SEP:17
 home built with U.S. products only, OCT:15

Metal roofing: *See* Roofing.

Moisture:

chimney chase, rotten, and details for proper drainage plane, NOV:23
 drywall, moisture-resistant (P), MAR:73
 EIFS sidewall detail (L), FEB:15
 floor heat cable, moisture-resistant (P), OCT:75
 roof ventilation for houses in wet coastal climate (Q), FEB:29
 Zip System sheathing panels, overview and installation details*, FEB:47; (L) JUN:17; (L) JUL:13

Nailers, brad, plug-in (P), MAR:91

OSHA: *See* Code, building; Safety, job-site.

Paints and finishes: *See also* Lead paint.

faux finishes on garage doors, APR:88
 high-quality finish for mixed substrates, details for*, OCT:53
 low-VOC claims questioned by Better Business Bureau, APR:19
 plant- and mineral-based oil paint (P), JAN:63
 rough drywall showing through paint (Q), FEB:29
 sprayer, airless (P), OCT:89

Plumbing:

fitting removal trick (L), JAN:13
 P-trap alternative, clog-free (P), JUL:81
 tools, cordless, review, AUG:71

Porches:

column, split, steel-post, installing for porch roof support, DEC:19
 porch enclosure with aluminum storm door panels, FEB:31
 porch rehab, from concrete piers to roof*, MAR:65
 Sonotube installation under decks and porches, FEB:31

Rainscreens: *See* Siding.

Rammed-earth walls, in upscale homes, OCT:96

Recycling: *See* Environment.

Remodeling: *See also* Restoration.

adding bath, expanding bedrooms in small house, APR:31
 apartment remodel for accessibility and HUD requirements*, SEP:67
 attic joists, stacking for living space expansion (Q), OCT:25
 energy retrofit, small house, in three phases*, JUL:43
 fire doors, automatically released, in condo expansion job*, AUG:61; (L) OCT:13
 Harvard reports remodeling comeback, APR:19
 ice dam repair, profitable sideline with*, JAN:29; (L) MAR:15; (L) APR:17; (L) MAY:15; (L) JUL:13
 kitchen expansion project, removing bearing wall for*, AUG:45; (L) NOV:15
 lead-paint power scrapers, comparison and review*, MAR:57
 narrow third-floor apartment, redesign for openness and storage*, MAY:61
 porch rehab, from concrete piers to roof*, MAR:65

standing-seam roof, restoring with elastomeric membrane*, FEB:55
 windows, details for weathertight installation*, FEB:65

Restoration, of wood windows, interest in, SEP:17; (L) DEC:13

Roofing:

cedar, valley for, and job profile, AUG:29
 concrete tile, installation details for reroofing job*, APR:39; (L) JUN:17
 fiberglass shingles, slate-look (P), SEP:81
 leak repair of flat roof with EPDM rubber*, OCT:39
 rubber, recycled (P), MAY:69
 smog-eating tile roofs in Calif., MAR:17
 standing-seam roof, restoring with elastomeric membrane*, FEB:55
 stone-coated steel (P), MAY:69

Roofs: *See also* Framing, roof.

dormer, prefab, details for building on ground and lifting*, DEC:59
 roof tile adhesive (P), NOV:65
 sheathing, weather-barrier (P), DEC:65
 soffit baffles, insulation-stabilizing (P), JUL:81
 underlayment, mineral-surface (P), AUG:65
 underlayment, sun-resistant (P), AUG:65
 underlayment with traction (P), MAY:69
 ventilation for wet coastal climate (Q), FEB:29
 vent pipe boot (P), MAR:73
 Zip System sheathing panels, overview and installation details*, FEB:47; (L) JUN:17; (L) JUL:13

Safety, job-site:

builder fined for fall-protection violations, NOV:19
 EPA RRP, getting on board with, JAN:15; (L) MAR:15; (L) APR:17
 hearing protection, radio headset, review, MAY:79
 injuries, number underestimated, NOV:19
 lead-paint power scrapers, comparison and review*, MAR:57
 OSHA fall-protection regs, delay in reinstating, AUG:17
 OSHA fall-protection regs, legal challenge rejected, JUN:25
 OSHA fall-protection regs reinstated, FEB:19; (L) MAR:17; (L) MAY:15
 OSHA regs and fines unmanageable (L), MAY:15
 safety glasses, stylish (P), FEB:69
 table-saw safety standard proposed, NOV:19
 welding helmets, fun (P), AUG:77

Sales: *See* Marketing.

Saws:

can light hole saw (P), MAY:85
 flooring-saw review, APR:79
 inline circular, comparison and review*, JUL:71; (L) OCT:13
 jigsaw blades (P), SEP:91
 miter, dual bevel glide model, review, FEB:73
 recip blade, demolition (P), JUL:91
 recip blade, easy-plunge (P), APR:83
 recip, tool-free (P), JUN:89
 sliding compound miter, review, NOV:71
 stabilizer/floor cart (P), NOV:75
 table, portable, review (P), OCT:75
 table-saw safety standard proposed, NOV:19

Security and lock systems, remote control deadbolt (P), AUG:65

Shingles: *See* Roofing.

Showers and tubs:

air baths, affordable (P), DEC:65
 geometric tubs (P), DEC:65
 hot-mop pans, absence of in JLC book (Q), AUG:27
 shower, solid-surface, replacement (P), DEC:65
 tub enclosure, surround-free (P), APR:73
 vertical spa, custom (P), APR:73
 walk-in tub (P), APR:73

Siding: *See also* Stucco.

aluminum brake (P), AUG:77

cedar shingle siding, installation details for*, MAR:33
 cleaner, nonacidic (P), APR:73
 cutter, cordless (P), NOV:75

EIFS sidewall detail (L), FEB:15

fiber-cement, premium (P), MAR:73

fiber-cement replacement job and energy upgrade*, SEP:57; (L) DEC:13

fiber-cement shakes, narrow (P), DEC:65

open-joint rainscreen, overview and installation details*, SEP:75

OSB, exposed, and structural soundness (Q), AUG:27

poorly finished drainage plane, fix for*, OCT:59

rainscreen siding kit, fiber-cement (P), FEB:69

Snakes, infestation in house, MAR:96

Solar power:

attic fan controller (P), JUL:81
 disputes over panel placement, OCT:15
 DOE decathlon won by U. Maryland, NOV:19
 homes with solar sell for more, JUL:21
 modular kit (P), FEB:69
 solar water heating storage tanks (L), FEB:15

Sprinklers: *See* Fire safety.

Stairs:

curved handrail, forming, and finessing the transitions*, JUL:55
 elliptical, framing approach using a trammel to scribe*, APR:49
 handrail, stainless-steel (P), DEC:65
 handrail, stainless-steel, installing, OCT:29
 jigs and tools for building stairs*, JAN:48
 modular (P), JUL:81
 railing system, prefab (P), JUN:75
 tread returns, pattern-routing technique for*, NOV:58
 winder stair layout and code compliance (L), MAR:15
 winders, wedge-shaped boxes for, OCT:29

Storage:

cedar closet lining (P), FEB:69
 closet carousel, accessible (P), NOV:65

Storms and storm damage:

2011 tornado damage, assessing, and APA recommendations*, SEP:43
 ICC 500 storm shelter code coming into use with demand, AUG:17
 shutters, transparent (P), JUN:75

Structural: *See also* Defects.

2011 tornado damage, assessing, and APA recommendations*, SEP:43
 attic joists, stacking for living space expansion (Q), OCT:25
 barn, reassembling on new site, SEP:96
 column, split, steel-post, installing for porch roof support, DEC:19
 deck requirements per 2009 IRC, overview and details*, JUN:69
 double-plywood substrate and load-bearing membrane under ceramic tile*, MAR:45
 failed hillside foundation, correcting with helical piers*, DEC:49
 freestanding deck, methods for stabilizing*, DEC:27
 insulated materials (P), APR:73
 kitchen expansion project, removing bearing wall for*, AUG:45; (L) NOV:15
 OSB, exposed, and structural soundness (Q), AUG:27
 spreading roof fix with horizontal beam and steel tie rod retrofit*, FEB:39

Stucco:

electrical boxes, flashing technique, AUG:29
 poorly finished drainage plane, fix for*, OCT:59

Taxes: *See* Business.

Tile: *See* Ceramic tile.

Timber-frame barn, built with tech ed students in slow economy, DEC:80

Toilets:

high-efficiency (P), MAR:73
 low-flow, re-engineered (P), SEP:81
 low-flow toilet problem in San Francisco, APR:19

2011 JLC Index

space- and water-conserving (P), OCT:75
super-high-end model, JUN:25

Tools & Equipment: *See also* Jigs; Nailers; Saws.
angle finder, digital sliding (P), SEP:91
angle square, preset (P), MAR:91
annual JLC Live show, product picks from*, JUL:64
annual STAFDA tool show, products from*, JAN:55
backup power, natural gas or propane (P), SEP:81
carpenter's pencil, solid-graphite (P), FEB:75
carrying cases, stackable (P), JUL:91
compressor, 500-psi, review, JUN:81
compressor, quiet (P), JAN:67
drill/driver, compact, review, DEC:71
drill/drivers, 12-volt, comparison and review*, JUN:51
driver cutter knife (P), NOV:75
drop cloth, breathable (P), MAR:73
floor cover, nonslip (P), JUL:81
gloves, cold-weather (P), JAN:67
grinder shroud (P), OCT:89
handle, suction, for lifting (P), NOV:75
hand tools, expanded line of (P), DEC:77
jacket, heated, cordless (P), NOV:71
jig, crown molding (P), JUN:89
jigs and tools for building stairs*, JAN:48
kilt, cotton, with tool pockets (P), JUN:89
laser, 3-in-1 (P), OCT:89
ladder levelers (P), SEP:91
ladder top-cap accessories (P), FEB:75
lead cords, red, white and blue (P), APR:83
lead-paint power scrapers, comparison and review*,
MAR:57
level, adjustable (P), APR:83

level, box-beam, electronic spirit, review of, MAR:85
level, LED-lit (P), JAN:67
levels, spirit (P), OCT:89
nail puller pliers (P), MAY:85
nails, engineered lumber (P), DEC:77
nibbler, tough (P), AUG:77
oscillating multi-tool adapter plate (P), FEB:75
oscillating multi-tools, comparison and review*,
MAY:45
pliers, high-leverage (P), JUL:91
predrilling and countersinking tool (P), APR:83
reveals, double-sided aluminum (P), MAR:91
screws and tools, a look at the ancient roots of,
FEB:80
screws, pocket, for decks (P), MAR:91
smartphone saves money for geezer (L), SEP:13
square, multipurpose (P), DEC:77
tape measure designed for dyslexics/easier reading,
JAN:15
torch, compact (P), FEB:75
utility knife, fixed-blade (P), MAY:85
utility knife, side-sliding, review, MAY:79
vac for heavy dust conditions (P), DEC:77
vac, HEPA, two-cord workaround (P), JAN:67
video scope (P), AUG:77
Trim: *See* Exteriors; Finish carpentry; Interiors.
Ventilation, mechanical:
basement fan (P), FEB:69
bath fan, quiet, efficient (P), AUG:66
Ventilation, roof: *See* Roofs.
Water conservation:
Colo. mandates options in new homes, APR:19

low-flow toilet problem in San Francisco, APR:19
on-demand circulation systems, overview and
benefits of (L), JAN:13; (L) FEB:15
rainwater pillow (P), SEP:81

Water heaters:

heat-pump (P), MAY:69
on-demand circulation systems, overview and
benefits of (L), JAN:13; (L) FEB:15

Water treatment, filter, heavy-duty (P), MAR:73

Weatherization: *See* Energy efficiency.

Wind: *See* Storms and storm damage; Wind power.

Windows:

block, movable (P), AUG:65
details for weathertight installation*, FEB:65
film, low-e (P), OCT:75
glazing area recommendations (Q), APR:27
June cover photo, window flashed correctly (L),
SEP:13
replacement, guide to understanding and choosing*,
OCT:65

replacement, installation profile, SEP:29
shades, battery-powered (P), NOV:65
skylights, insulated (P), OCT:75
skylights, tubular (P), MAY:69
skylight, tubular, dimmer (P), FEB:69
wood, interest in restoring, SEP:17; (L) DEC:13

Wind power, zero-carbon house with wind and
geothermal (L), JAN:13

Wood flooring:

flooring-saw review, APR:79
salvaged hardwood flooring (P), FEB:69

Wood tiles, mosaics (P), OCT:75